Sanitized Copy Approved for Release 2010/07/02 : CIA-RDP89-00244R001102650006-6

Sent
Paul / Andy.

Report for Rombo's.

- 4th floor power in E&F INTERSECT Welds not completed.
- In Center section ground floor. Part Graded / Part ungraded Gravel not 4" thick throughout.
- Two Slab pours on basement long Crack appearing.

STAT

STAT

GSA

Sb.d This was ground chng.

STAT

Sanitized Copy Approved for Release 2010/07/02 : CIA-RDP89-00244R001102650006-6